# Scotch-Weld<sup>™</sup> Low Odour Acrylic Adhesives DP8825NS Green

### **Preliminary Product Data Sheet**

Date: November 2016 Supersedes: New

#### **Product Description**

 $3M^{\text{TM}}$  Scotch-Weld  $^{\text{TM}}$  Low Odour Acrylic Adhesives are high performance, two-part acrylic adhesives with lower odour than most acrylic adhesives.

#### **Key Features**

- Toughened
- Work life approximately 25 minutes
- Excellent shear strength
- · Outstanding peel and impact strength
- · 10:1 mix ratio
- · Increased cure speed with applied heat
- Contain glass beads (250µ diameter) to control bond line thickness

#### Note:

Unless otherwise indicated, all properties measured at 22 °C.

#### **Physical Properties**

	DP8825NS Green				
Colour	Base (B) Accelerator (A)	Off white Blue			
Viscosity <sup>1</sup>	Base (B) Accelerator (A)	35000 mPas 15000 mPas			
Density <sup>2</sup>	Base (B) Accelerator (A)	1.12 g/cm <sup>3</sup> 1.08 g/cm <sup>3</sup>			
Mix ratio	By volume By weight	10 Parts B : 1 Part A 10 Parts B : 1 Part A			
Note: Cure speed times are approximate and depend on adhesive temperature.					
Work life <sup>3</sup>		22-24 min			
Open time <sup>4</sup>		20-22 min			
Time to handling strength <sup>5</sup>		42-46 min			
Time to structural strength <sup>6</sup>		50-56 min			
Full cure time		24 hours			
·					

<sup>1.</sup> Viscosity measured using cone-and-plate viscometer; reported viscosity at 4 sec<sup>-1</sup> shear rate.

<sup>2.</sup> Density measured using pycnometer.

<sup>3.</sup> Maximum time that adhesive can remain in a static mixing nozzle and still be expelled without undue force on the applicator.

<sup>4.</sup> Maximum time allowed after applying adhesive to one substrate before bond must be closed and fixed in place.

<sup>5.</sup> Minimum time required to achieve 0.35 MPa of overlap shear strength.

<sup>6.</sup> Minimum time required to achieve 7.0 MPa of overlap shear strength.

#### Typical Mixed Physical Properties

Property	DP8825NS Green	
Colour	Green	
Full cure time	24 hours	
Viscosity	35000 mPas	
Density	1.12 g/cm <sup>3</sup>	

## Typical Cured Physical Properties

Overlap Shear (MPa)7

Substrate	DP8825NS Green		
Aluminium	21,0 CF		
Stainless steel	18,5 CF		
PVC	9,6 SF		
ABS	8,8 SF		
Acrylic	7,1 SF		
Polycarbonate	6,5 AF		
Polystyrene	3,8 AF		
Polyester (fiber-reinforced)	6,1 AF		
Epoxy resin (fiber-reinforced)	18,8 CF		
Aluminium (tested at 82°C)	4,9 CF		

<sup>7.</sup> Overlap shear values measured using ASTM D1002; 1 min open time; adhesive allowed to cure for 24 hours at room temperature; 12.5mm overlap; 250 micron bond line thickness; samples pulled at 0.1 in/min for metals and 50mm/min for plastics; all surfaces prepared with light abrasion and solvent clean; substrates used were 1.5mm thick metals and 3mm thick plastics; failure modes:

AF: adhesive failure

CF: cohesive failure

SF: substrate failure

**Note:** Environmental aging tests have shown that these adhesives may accelerate the corrosion of certain metals (such as bare steel, copper, brass, and bronze), leading to low bond strength values and early bond failure. These adhesives also have relatively low adhesion to low surface energy plastics (such as polypropylene, polyethylene, TPO, and PTFE). Applications involving any of these materials should be carefully evaluated by the end user for suitability.

Floating Roller Peel (N/mm width)8

Substrate	DP8825NS Green	
Aluminium	5,2 CF	

8. Floating roller peel values measured using ASTM D3167; adhesives allowed to cure for 24 hours at room temperature; 25mm wide samples; 0.44mm bond line thickness; samples pulled at 150mm/min; aluminium surfaces etched; substrates used were 1.5mm thick and 0.5mm thick aluminium; failure modes:

AF: adhesive failure

CF: cohesive failure

SF: substrate failure

**Note:** The data in this sheet were generated using the 3M™ EPX™ Applicator System equipped with an EPX static mixer, according to manufacturer's directions. Thorough hand-mixing will afford comparable results.

#### Environmental Resistance<sup>9</sup>

Condition	Substrate	DP8410NS Green
150 °C	Aluminium	100%
50 °C + 80 % relative humidity		75%
85 °C + 85 % relative humidity		30%
Water		60%
Salt water (5 wt % in water)		75%
Diesel fuel		100%
Motor oil		100%
Antifreeze (50 wt % in water)		90%
Isopropyl alcohol		65%
Bleach (10 w t% in water)		75%
50 °C + 80 % relative humidity		90%
Water	PVC	100%
Salt water (5 wt % in water)		100%
Hydrocloric acid (16 w % in water)		100%
Sodium hydroxide (10 wt % in water)		65%

<sup>9.</sup> Values indicate overlap shear test performance retained after 1,000 hours of continuous exposure relative to a control sample left at room temperature; samples conditioned for 24 hours at room temperature and 50% relative humidity prior to tests; "NT" = not tested yet.

**Note:** Fully cured Acrylic Adhesives can withstand short-term incidental contact with almost any solvent, chemical, or environmental condition. However, long-term continuous exposure to the following liquids should be avoided:

Elevated temperature (>40°C) water Ketone-type solvents (acetone, MEK)

#### **Directions For Use**

1. To obtain the highest strength structural bonds, paint, oxide films, oils, dust, mould release agents, and all other surface contaminants must be completely removed. The amount of surface preparation depends on the required bond strength and environmental aging resistance desired by user. For suggested surface preparations on common substrates, see the section on surface preparation.

#### 2. Mixing

#### For Duo-Pak Cartridges

Store cartridges with cap end up to allow any air bubbles to rise towards the tip. To use, simply insert the cartridge into the EPX applicator and start the plunger into the cylinders using light pressure on the trigger. Then remove the cap and expel a small amount of adhesive to ensure material flows freely from both sides of cartridge. For automatic mixing, attach an EPX mixing nozzle to the cartridge and begin dispensing the adhesive. For hand mixing, expel the desired amount of adhesive and mix thoroughly. Mix approximately 15 seconds after obtaining a uniform colour.

#### For Bulk Containers

Mix thoroughly by weight or volume in the proportion specified on the product label or in the typical uncured properties section. Mix approximately 15 seconds after obtaining a uniform colour.

3. Apply adhesive and join surfaces within the open time listed for the specific product. Larger quantities and/or higher temperatures will reduce this working time.

- 4. Allow adhesive to cure at 16 °C or above until completely firm. Applying heat up to 66 °C will increase cure speed.
- 5. Keep parts from moving during cure. Apply contact pressure or fixture in place if necessary. Optimum bond line thickness ranges from 0.1 to 0.5 mm; shear strength will be maximized with thinner bond lines, while peel strength reaches a maximum with thicker bond lines.
- Excess uncured adhesive can be cleaned up with ketone type solvents.\*

\*Note: When using solvents, extinguish all ignition sources, including pilot lights, and follow the manufacturer's precautions and directions for use.

#### **Surface Preparation**

3M<sup>™</sup> Scotch-Weld<sup>™</sup> Acrylic Adhesives are designed to be used on metal, wood and most plastic surfaces. The following cleaning methods are suggested for common surfaces:

#### Steel:

- 1. Wipe free of dust and dirt with pure solvent such as acetone or isopropyl alcohol.\*
- 2. Sandblast or abrade using clean fine grit abrasives.
- 3. Wipe again with clean solvent to remove loose particles.\*
- 4. When using a primer, apply within 4 hours after surface preparation.

#### **Aluminium:**

- 1. Wipe free of dust and dirt with pure solvent such as acetone or isopropyl alcohol.\*
- 2. Sandblast or abrade using clean fine grit abrasives.
- 3. Wipe again with clean solvent to remove loose particles.\*

#### Plastics/Rubbers:

- 1. Wipe with isopropyl alcohol.\*
- 2. Abrade using fine grit abrasives.
- 3. Wipe with isopropyl alcohol.\*

#### Glass:

- 1. Solvent wipe surface using acetone or MEK.\*
- 2. Apply a thin coating of a silane adhesion promoter to the glass surfaces to be bonded and allow to dry completely before bonding.

\*Note: When using solvents, extinguish all ignition sources, including pilot lights, and follow the manufacturer's precautions and directions for use.

#### Storage & Shelf Life

#### Storage

Store at 16  $^{\circ}\text{C}$  - 25  $^{\circ}\text{C}$  and 40-65 % relative humidity in its original box.

The product can be stored up to 18 months after production.

**Note:** The shelf life may be shortened if the original packaging is not properly sealed or stored in an environment with high temperatures or humidity.

#### **Precautionary Information**

Refer to product label and Material Safety Data Sheet for health and safety information before using the product.

For information please contact your local 3M Office.

www.3M.com

#### For Additional Information

To request additional product information or to arrange for sales

assistance, call.....

Address correspondence to: 3M

#### **Important Notice**

All statements, technical information and recommendations contained in this document are based upon tests or experience that 3M believes are reliable. However, many factors beyond 3M's control can affect the use and performance of a 3M product in a particular application, including the conditions under which the product is used and the time and environmental conditions in which the product is expected to perform. Since these factors are uniquely within the user's knowledge and control, it is essential that the user evaluate the 3M product to determine whether it is fit for a particular purpose and suitable for the user's method or application. All questions of liability relating to this product are governed by the terms of the sale subject, where applicable, to the prevailing law.

Values presented have been determined by standard test methods and are average values not to be used for specification purposes. Our recommendations on the use of our products are based on tests believed to be reliable but we would ask that you conduct your own tests to determine their suitability for your applications. This is because 3M cannot accept any responsibility or liability direct or consequential for loss or damage caused as a result of our recommendations

3M and Scotch-Weld are trademarks of the 3M Company.

3M United Kingdom PLC 3M Centre, Cain Road Bracknell Berkshire RG12 8HT

Tel: 0870 60 800 50 www.3M.co.uk/adhesives

3M Ireland Ltd The Iveagh Building The Park, Carrickmines Dublin 18 00353 (01) 280 3555